

From: George Morino/=TMS/Toyota.

Sent: 10/17/2007 4:15 PM.

To: [-] Takezo Oba/=HINPO/TMC0@TMC0@TMCE.

Cc: [-] .

Bcc: [-] .

Subject: Fw: Closing Resume of the Lexus AWFM Investigation.

George Morino
National Manager
Quality Compliance Department
Product Quality and Service Support
Toyota Motor Sales, U.S.A., Inc.
Tel. 310-468-3392
Fax 310-468-3399

NOTICE: This email message and all attachments transmitted with it are intended solely for the use of the addressee and may contain legally privileged and confidential information. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, copying, or other use of this message or its attachments is strictly prohibited.

If you have received this message in error, please notify the sender immediately by email reply and please delete this message from your computer. Thank you.

----- Forwarded by George Morino/TMS/Toyota on 10/17/2007 04:15 PM -----

Chris Santucci/WDC/Toyota_NY@TOYOTA_NY
10/17/2007 12:10 PM
To Michiteru Kato/HINPO/TMC0@TMC0@TMCE@TOYOTA
cc George Morino/TMS/Toyota@Toyota, Kirk Forsht/TMS/Toyota@Toyota, ctinto@tma.toyota.com, Kevin
Ro/WDC/Toyota_NY@Toyota_NY
Subject Closing Resume of the Lexus AWFM Investigation

Attached is a copy of the closing resume of the Lexus ES350 AWFM investigation. I have read it, and it is written very strangely, like a series of random, disconnected thoughts. I don't really know how to write this up, other than the investigation must be closed, because we now have the closing resume.

NHTSA points out that the mat must be unsecured to interfere with the accelerator pedal. They discuss a scenario that could potentially lead to an extended, runaway vehicle incident where the brakes can overheat. They also mention a fatality, but give very few details - like make or model of the vehicle, or whether or not AWFM's were in the vehicle.

They also do not include their blanket statement closing the investigation, nor do they mention their right to re-open if new evidence presents itself. However, in the last paragraph, they note that this can happen in any vehicle and include a cautionary statement to that effect. Please review, and comments are appreciated. I am wondering what others think about this document, and if anyone believes a follow up needs to be made with NHTSA for clarification.

Regards,

Chris Santucci - Assistant Manager
Technical and Regulatory Affairs
Toyota Motor North America, Inc.
Ofc (202) 463-6856 Cell (202) 651-1581 Fax (202) 463-8513
email: Chris_Santucci@tma.toyota.com

Note: We cannot receive attachment extensions listed below.
.exe, .com, .pif, .scr, .cmd, .bat, .vbs, .lnk, .htm, .html, .shs, or .zip